





The **1844** Difference

Achieve a superior gloss with **1844** floor finish! **1844** is non-yellowing and non-powdering with an excellent response to burnishing — features that will extend your strip cycles and save significant labor hours!

Floor finish application is easy with **1844**'s selfleveling feature. The result is an extremely durable floor that holds up to the heaviest traffic. **1844** may be applied to virtually all hard floor surfaces, providing shine and protection beyond your expectations. **1844** may be used with all burnishing programs.

FEATURES	ADVANTAGES	BENEFITS
Superior gloss	Presents professional image	Improves worker morale Increases customers' confidence in cleanliness standards
Sealer/Finish combination	Eliminates need for a sealer	Reduces customers' inventory & reduces costly application errors
Self-leveling	Coats are easy to apply	Reduces dollars spent to repair streaked floors Reduces the need for designated floor crews
Non-yellowing	Lengthens time between strip outs	Reduces recoats/cuts labor costs
U.L.® listed for slip resistance	Reduces slip & fall liability	Provides a shiny but safer walking surface
Extremely durable	Doesn't powder when burnished	Reduces recoats/cuts labor costs
Versatile	Can be used with all burnishing programs & on most floor surfaces	Reduces dollars needed for inventory of multiple finishes
Excellent response to burnishing	Improves worker morale for a job well done Consistently shiny floors	Increases customers' confidence in cleanliness standards

Available Packaging





DIRECTIONS FOR USE

FLOOR PREPARATION:

- Strip floor thoroughly, using a Buckeye floor stripper: Revelation[®], RipSaw[™], Juggernaut[®], or Penetrate[®].
- 2. Rinse floor with clear water, changing rinse water frequently to prevent redepositing of dirt and stripper residue.
- 3. Allow floor to dry thoroughly before applying **1844**.

APPLICATION:

- 1. Use a clean mop and clean bucket.
- 2. Saturate mop with 1844.
- 3. Press mop into wringer to remove excess finish. Do not wring mop.
- 4. Allow each coat to dry 30–45 minutes under normal room conditions.

MAINTENANCE:

- 1. Dust mop floor.
- Damp mop as required, using Buckeye Blue, Straight-Up[®], Crossbow[®], Tenacity[®], True 7[™] or Buckeye Green Light[™].
- 3. Spray buff or burnish **1844** with Buckeye **Equity**[™] or **R.P.M.**[™].

TECHNICAL SPECIFICATIONS			
pН	7.7 ± 0.2		
Weight/Gallon	8.54 lbs		
Sediment (based on volume)	Less than 0.1%		
Film Color	Water Clear		
Odor	Bland		
Flash Point	None		
Heat Stability	Over 30 days @ 125° F		
Freeze-Thaw Stability	Pass 3 Cycles		
Storage Stability	Excellent*		
Slip Resistance	UL Classified		
*stored in its original unopened container			

